

12th September, 1941.

Im.1.39.

22 JAN 1942

8A

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Gandara

Rpt.

No. 2754

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

Nature of Survey

DAMAGE.

The *Port Said* Surveyors report this vessel examined afloat on account of damage through *Enemy Action*. *Sheerstrake plate No 1 and forecastle side plates nos 2 & 3. (S.S.) found holed by shrapnel*

Temporary repairs have been effected to their satisfaction, and the Surveyors recommend *permanent repairs at the Owner's Convenience.*

It is submitted the vessel is eligible to remain as classed without record of survey, subject as recommended.

as now, subject, etc.

The Certificate of Classification to be endorsed "*Cargo buttons not fitted*" and the same notation to be printed in the Register Book.



67A.
© 2019
22.1.42.

Lloyd's Register
Foundation

W40-0055