


S.S. "GANDARA".  
-----

It is submitted the Gibraltar Surveyor be informed  
it is noted that the damage to the frames in No.1 Hold only  
extends for two strakes above the level of the tank top.  
In the circumstances the extent of the <sup>new</sup> reversed bars may be as  
proposed by the Surveyor. Efficient straps must be provided  
connecting the new 9 inch frames to the original 10 inch  
frames.

It is noted that it is proposed to use plates and  
frames, in the repairs, which have been tested by the Admiralty.  
The Surveyor should <sup>first</sup> forward to this Office the particulars  
of such tests.

  
27.4.27.



© 2019

Lloyd's Register  
Foundation

W40-0070