

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME STEEL S.S. "GANDARA" Rpt. Mab. No. 10517

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

verse No. 83.0 Depth "d" 18.4'
 ng: Table No. 3 Description Bulb angle as approved.
 tudinal No. 33200
 Proportions Length = 10.2
 Depth =

ridge Deck Sheerstrake as approved.

The Downton Pump has been dispensed with for the present, but
 is concluded the Owners are agreeable to fit same when requested.

This vessel appears to have been built in accordance with the
 and the approved plans, and it is submitted she is eligible to
 lassed ☒ 100 A.1. (steel) as recommended.

2 Dks. (steel)

Cell DB 336' 10 1/2 t. FPT 128 t. APT 207 t.

FK. 7BH. cem. Lloyd's A & C.P. P49', B113', F40'

The Certificate of Classification, to be endorsed
 "Cargo battens not fitted," and the same
 notation to be printed in the Register Book.

aes
 4-11-19



© 2019

Lloyd's Register
Foundation