

Do. in peaks
Do. in way of Double Bottoms at Solid Floors...

3 1/2	3 1/2	36	3 1/2	3 1/2	36
8	2 1/2	46	8	2 1/2	46

Quarter 'tween Dks., ing Rivs,
" in Hold " "

TELEPHONE Nos 7 & 8.

TELEGRAMS:—"JET, SUNDERLAND."

ROBERT THOMPSON & SONS LTD
SHIPBUILDERS & REPAIRERS.

*Southwick Yard,
Sunderland.*

ALSO AT
BRIDGE DOCKYARD.

4th April 19 24.

Messrs. Lloyds Register of Shipping,
SUNDERLAND.

Dear Sirs,

s. s. No. 320.

With reference to the second paragraph of
your letter of the 12th March 1923, we beg to confirm that
we had the sanction of the Owners to construct the above
vessel in accordance with the Rules which came into force
in January 1923.

Yours faithfully,

FOR ROBERT THOMPSON & SONS LTD.

[Signature]
Secretary



© 2020

Lloyd's Register
Foundation

W403-0066

Spacing

Every frame | Every frame.

RS.
teabov
tal Plat
.....
.....
.....
length
len
Angle
len
Angle
f.....
length
Angle.
thickne
f Bridg
thickne
f Bridg
Bridge
re an
ways.
ll
ge) ...
idge) .
& thick
.....
is
& thick
.....
r Pla
thickn
Hatch
& thick
.....
Ste
& thick
.....
Steel
th & th
Steel
id
hole or