

WRECK SECTION.

No.

512.

1 OCT 1941

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME LEONIDAS Z. CAMBANIS Rpt. Hfx No. 3426

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd S.S. No. 3 became due 1.41.

For conditions of class see endorsement

3.2.41.

The HALIFAX N.S. Surveyors report (3.41) the vessel afloat and an examination made for leakage in No. 1 tank. 6 rivets missing and 4 loose (p.s) in this tank close to collision bulkhead have been dealt with temporarily by fitting bolts and cement, and the Surveyors recommend permanent repairs at the next dry docking.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended and as above.

As Now, Subject, etc.

Note The vessel sunk by submarine in April last and particulars have been omitted from the R.B.

© 2021

W411-0058

The above recommendations were carried out satisfactorily.