

to Chief Surveyors 27.9.17.

SEL'S NAME Shells Glenary

Received from Chief Surveyors

Report

No. 37133

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

When due

100 A-1 (Steel)

3 Ds. (Steel)


Call D.B. 330 9806. F.P.T. 556 A.P.T. 466

FK. T.B.H. pl Cam. Length 31. B84' F 42

[Signature]
27.9.17

The Glasgow Surveyors should be requested to forward the report of the collision bulkhead was fitted.

[Signature]
27.9.17



© 2021

Lloyd's Register Foundation

W41 0185