

HARPALION

3 MAR 1942


It is submitted before this case receives consideration, the Leith surveyors should be informed the vessel requires 270 fathoms of chain cable, and that 285 fathoms were recently reported on board. They should be requested therefore, to state if they are correct in reporting only 240 fathoms now on board the vessel.

the discrepancy

to explain

*Leith
6/3/42*

*6/1/42
26.2.42*



© 2020

Lloyd's Register
Foundation

W42-0116

Soundings taken, but no evidence of leakage was

*with
Leith
d to
Leith*