

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME MEREL Rpt. LON. No. 107888**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.Damage through *collision*

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	3	8				2	3
Removed and faired or repaired.....	2					1	
Faired or repaired in place.....	4	4				1	2

Other items:-

*Vessel placed in dry-dock, bottom coated,
upper stem bar, hawse pipes, lower anchor and
1 length chain cable renewed and minor repairs
effected*

It is submitted the vessel is worthy to remain as classed with
record of Survey 10-39.

100 A-1.
with fbd
10-39 Lon.



© 2020

Lloyd's Register
Foundation
W429-0008