

total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

CHARACTER.
X for Special Survey.
Date of last Survey and of
Periodical Surveys.

5m.10.38.

20 APR 1939

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "VENDIA" Rpt. Cpn. No. 10851

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented bottom and side shell plating, port and starboard, being dealt with at the Owners' convenience.

The Copenhagen Surveyors report the vessel placed on a slipway, bottom cleaned and coated and on account of damage through groundings, striking dock, quays, and during heavy weather, 7 shell plates renewed, a considerable number of shell plates, frames, floors faired or repaired and minor repairs carried out.

The indented bottom and side plating, as above, has now been dealt with.

It is submitted the vessel appears worthy to remain as classed with record of survey 3,39, without special condition.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

100A1) Without etc.
3,39 Els.)

Frames part examined good
Reverse Frames ✓
Longitudinals ✓
Transverses ✓
Floors part examined good

Have pumps been examined and found efficient? no
Have Sluice Valves been examined and found efficient? none
Have Watertight Doors been examined and found

Planking
Caulking
Treenails
Breasthooks & Stemson

Equipment letter
Anchors, No. of
Cables (State if non
length
(on board)

W465-0071

Lloyd's Register
Foundation