

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME ENGLAND Rpt. CPN No. 11026

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Survey DAMAGE.

Damage through *striking quay*

now repaired as follows:-

	Shell Plates	Main Frames	R. Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Vessel placed in dry dock, bottom coated repairs to bilge keel forward and bulwark aft, port side

It is submitted the vessel is worthy to remain as classed with record of Survey 10-39

*100 A-1.
10-39 ELS.*

*was
20.10.39* *EL*



© 2020

Lloyd's Register Foundation

W462-0056

RETAIN

4 NOV 2020

10:00 AM



© 2020

Lloyd's Register
Foundation

UND

NET

Stutt

Cell

tota

N

Las

(Period

costs

called

sho

size

sho

resp

In dat

of

REPA

Nov

fol

SUMMA

R

R

F

PRESENT

Decks ...

Gaulking

Coaming?

Beams &

Outside I

"

Frames

Reverse

Longitud

TRANSVER

Floors ...

Keelcons

Stringers

Inner Bo

Have the

Have the

Gem

ENGLAND

mittee's