

Was a damage report made by anyone else? If so, by whom?

REPAIRS OR EXAMINATION AS PER RULE, FOR

Condition

Chief Ship Surveyor

Received from Chief Ship Surveyor

24 JUL 1935

NAME

"BURMESTAN"

Rpt.

Cal

No.

9458

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Survey

The Calcutta Surveyors report this vessel placed in dry dock, bottom coated and two bow plates renewed; also 5 lengths of chain cable.

It is submitted the vessel appears/worthy to remain as classed with record of survey 6,35.

LOCAL  
Shade dk  
6,35 Cal



22.7.35

Lloyd's Register Foundation

W466-0017

this survey, thus, for example:—".....to remain as now classed in the Register BOOK without fresh record of survey, to remain as classed survey 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is in good condition & is liable in our opinion to remain as classed