

Time of Receipt



POST OFFICE

TELEGRAM.

If the accuracy of this  
can be repeated under spec. 1. 20.  
obtained on application at the Office from

This form must accompany any inquiry made respecting this telegram.

Office of Origin and Service Instructions.

Charges

to pay

Office Stamp



Received here at  
5.59 P

M.

Lorient 27 8.56.

Lloyds Register  
71 Fenchurch St London  
Steamer Giral Bottom  
Damage Starboard side  
in way of division  
between number three and  
four Tank just below mainmast  
have surveyed it and  
consider most probably caused

Sch. 29.

by grounding Starboard  
lower stock and plate  
twisted statement caused  
by touching Rock. Quite  
feasible in my opinion  
Demarest



2020  
Lloyd's Register  
Foundation

, Ltd. Sch. 29.

W48-0051



TELEGRAM.

For the chief of the surveyor

a.d.

Storm ~~my~~ gone  
broke

promised to be  
delivered  
Oct. 20. 17.  
of the  
of the



© 2020

Lloyd's Register  
Foundation