

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

7th October, 1915

Dear Sir,

With reference to Glasgow Report No. 35489 on the Machinery of the S.S. "WHEATSHEAF", I shall be glad if the Surveyors will state whether the after end of the screw shaft liner is made watertight in the propeller boss, also the number and size of the donkey boiler safety valves, pressure to which they are adjusted, if fitted with easing gear, if steam can enter from the main to the donkey boiler, and where the donkey boiler is fitted; as these particulars are not given on the report.

I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register  
Foundation

W487-0149