

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME s.s. "ATLANTEN" Rpt. cfr. No. 51020

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Survey _____

The class is subject to some indented plating and damaged frames on the Port and Starboard sides being dealt with at the Owners' convenience.

The riveting of the tunnel stools requires to be specially examined and dealt with as necessary at the Special Survey (See Got. 10056, form 9).


The 3rd Special Survey No.2 became due 11.34 and a proposal to postpone same until November next has been agreed to.

2 The Cardiff Surveyors now report the vessel placed in dry dock on account of damage due to heavy weather, and repairs effected to steering gear connections, the steering gear overhauled and a deck plate, found fractured at a hatch corner, renewed and minor repairs carried out.

The indented plating and damaged frames as above examined and found efficient.

It is submitted action be deferred.

[Handwritten signature]
27.5.35



© 2020

W490-D149 Lloyd's Register Foundation

If the Vessel has been
of the tanks examined. A
holders, and of the inner b

st Report,

ical Surveys, when
se of Repairs, if any
account of Damage
besides being detai
lacement of Anchors
back of this form.

age cases where t
ered his services f

IRS, OR EXAM

auto
of 22
from
Rural
man
the
fitted
Stunt
up
o. see

OF DAMAGE REPAI

ed
and Faired or Rep
or Repaired in place
EDITION OF THE

etc
ings
8
way of sidelights

Observ
clearly wheth
thus, for ex
or "to rem

ion 29)
Fee (if a
Expenses (if chargeable
Major's Fee (if any)

ittee's Minu

Report from Chief Ship Surveyor

No. 11120

of the Chief Ship Surveyor are based on the case for the consideration of the Insurance Commission

is subject to some intended repairs
and damaged the
port and starboard sides being dealt
with at the
The
of the Channel at the necessity of the Special Survey
The
proposed to be carried out in the case of the vessel
The vessel has been agreed to
the report the vessel placed
to leave whether any repairs
the steering gear, overhead
and a deck plate, found fractured at a hatch corner, necessary for
minor repairs carried out.

in any dock on account of damage to the vessel
affected to steering gear connections, the steering gear, overhead
and a deck plate, found fractured at a hatch corner, necessary for
minor repairs carried out.

the intended repairs and damaged frames as above
examined and found satisfactory.
If an additional action be deferred.

RETAIN



© 2020

Lloyd's Register
Foundation