

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.

6th August, 1915.

Dear Sirs,

Reverting to my letter of the 28th and your reply of the 29th June respecting the steamer "ALBUERA", I beg to acquaint you that the Committee have today had before them a report from the Society's Surveyors at this port from which it appears that two shell plates at the after end of the bridge are indented; and I think it well to inform you that it is recommended that repairs be effected at the first convenient opportunity.


The Surveyors further report that the new donkey boiler will be fitted next trip, and I have to say that in the circumstances the vessel's class is subject to the donkey boiler now on board not being used again.

I am, Dear Sirs,

Yours faithfully,

C. Salvesen & Co.,
29 Bernard Street,
Leith.

Secretary.



© 2020

Lloyd's Register
Foundation

W490-0165