

The 1st S.S. No 3 became due 9.31.

Surveyors 21.8.35

Received from Chief Surveyors

NAME *SSC "MONTAUK"*

Report *N. YK.*

No. *36199*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Condition

When due

*Subject to indented plating on port side being dealt with
at the Owners' convenience.*

N.Y.K.
22.8.35

*The vessel is proceeding to Italy to be broken up & the Italian Surveyors
should be requested to inform this office, when the work of demolition has
commenced*

RETAIN



© 2020

Lloyd's Register
Foundation

VB=Cell
otal cap
-N.B.-All
If the Va
the tanks ex
orders, and of
ast R
eriodical S
cause of Rep
on account o
and besides
replacement
the back of
damage cas
offered his
PAIRS, OR
hnd a
v juw
the die
rtton
leams
famie
ripes a
r ear
the Vis
ART OF DAMA
Renewed ...
Removed and F
Faired or Repai
NT CONDITION
g of Decks ...
rs ...
& Fastenings ...
Plating ...