

Subject to permanent repairs to indented  
shell plating (p & s.)

124 JUL 1939 1

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

LOCHAYON

Rpt.

Rot.

No. 28367<sup>a</sup>

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

Damage through

striking quay (Dws 22069 & hpt 24084)

now repaired as follows:-

|  | Shell<br>Plates | Main<br>Frames | R<br>Frames | Floors &<br>Bracket<br>Floors | Inner<br>Bottom<br>Plates | Deck<br>Plates | Beams |
|--|-----------------|----------------|-------------|-------------------------------|---------------------------|----------------|-------|
| Renewed .....                          | 1               | -              | -           | -                             | -                         | -              | -     |
| Removed and faired<br>or repaired..... | 1               | -              | -           | -                             | -                         | -              | -     |
| Faired or repaired<br>in place.....    | 1               | 9              | -           | -                             | -                         | (stringer)     | -     |

Other items:-

Other minor repairs effected

It is submitted the vessel is worthy to remain as classed without  
record of Survey & without special condition.

As now, without re.



© 2021

Lloyd's Register  
Foundation

W 500-0095