

Undertaking base

Report 6. 8. 35

Received from Chief Surveyors

ME 1/2 London Citizen

Report done

No. 99889

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

2nd S.S. No 1

When due 7.33

Still laid up per Lloyd's Index

! General Examination

The 2nd S.S. No.1 became due 7,33.

The ship has been laid up since January 1933 and the owners have furnished the usual undertaking.

According to Lloyd's Daily Index the ship is still laid up.

It is submitted for consideration whether, as 2 years have elapsed since the Special Survey became due, a general examination should be asked for.

W. 8. 35

W. 8. 35

© 2021

Lloyd's Register
Foundation

W 500-0280