

2m,3,42.

28 MAY 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "LAPLACE" REPORT L.A. No. 8301.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(The 2nd S.S. No.2 became due 6,39 and partly held 4,40).

A notation of 'Examined 11,41' valid for 12 months has been assigned.


For conditions of class see Endorsement 20.4.42.

The Lloyd's Agent Surveyor at SANTOS reports (3,42) the vessel examined afloat on account of leakage in fore peak tank and further temporary repairs effected to stem and stem plating as above.

The Surveyors recommends ~~xxx~~ permanent repairs at the first opportunity.

It is submitted the vessel appears worthy to remain as classed subject as above but amend as regards repairs to damaged stem.

As now, subject etc.



© 2021

S.S. PART HELD.

Lloyd's Register Foundation

W 51 - 0008