

5c.12.25.

*R. 2. 16.***F.E.**

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *St. Se. LUCRECIA.*Rpt. *Li*No. *8045.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

st. Long
 Transverse No. *4575*
Depth "d" *✓*Framing: Table No. *✓*Description *✓*Longitudinal No. *19835*

Proportions

Length

Depth = *13.99*

Deck Sheerstrake

*As approved.**Revised Rules.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A. 1. (stb). Carrying Petroleum in bulk.
 1 Stk (stb). Longitudinal framing at bottom & deck.
 FPT 107 C. APT 84 C. Lloyds. A & C.P.
 9 (see made report 8192)
 F.K. X B.H. ft. cum & ft. Asp.
 Q 89'. Lunk 187' F 39'
 Machy aft.



© 2021

 Lloyd's Register
 Foundation

WSI-0053

Solid Floors, thickness and spacing

Are Frame and Reversed Frame?

Bridge Deck, Angle, [or [.....