

on the... and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on

LLOYD'S REGISTER
7 - JULY 1937
Assd. 7.6.
LONDON

Time of Receipt.....

TELEGRAM.

to pay
_____d
ED
Telegraph
C.I.

No. 312
OFFICE STAMP



Prefix. Time handed in. Office of Origin and Service Instructions. Words.
m **27**



127 11.9 NEWCASTLEONTYNE T 13

To

MITTEE FEN LDN =

KIRNWOOD OUR LETTER 3 RD REGARDING RUDDER
PLEASE REPLY TONIGHT = REGISTER + 3 +

For free repetition of doubtful words telephone "TELEGRAMS ENQUIRY" or call, with this form at office of delivery. Other enquiries should be accompanied by this form and, if possible, the envelope.

B or C
C



© 2021

Lloyd's Register
Foundation
W51-0110
W51-0111

Special Damage or Repair Fee (if any).....£ 3 3 : 0

Received by me,

P. D. ...

Referred to the Chief Ship Surveyor.

MB

7 JUN 1937



© 2021

Lloyd's Register
Foundation

Special De...

ENCLOS



RAMS

(Periodic
cause o
on acco
and be
replace