


and besides being retained... replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

ALL CORRESPONDENCE SHOULD BE ADDRESSED TO THE FIRM AND NOT TO INDIVIDUALS

CONSTANTINE LINE

TELEGRAMS:
CONSTANT MIDDLESBROUGH
TELEPHONE 3445

JOSEPH CONSTANTINE STEAMSHIP LINE LTD
CONSTANTINE SHIPPING CO. LTD



LONDON OFFICE,
JOSEPH CONSTANTINE & SONS, (LONDON) LTD.
BALTIC EXCHANGE CHAMBERS,
24, ST MARY AXE,
LONDON, E.C. 3.

CANADIAN OFFICE,
JOSEPH CONSTANTINE STEAMSHIP LINE LTD.
309, BOARD OF TRADE BUILDING,
MONTREAL, P. O.

MARITIME BUILDINGS,

Technical Department MIDDLESBROUGH.
C/5. 15th January, 1937

Lloyd's Register of Shipping,
LONDON E.C.3.



Dear Sirs,

s.s. "KIRNWOOD".

You will probably have records showing that this vessel's Rudder was converted into an Oertz type at Messrs. John Headhead & Sons Ltd., South Shields in February 1929.

We are now contemplating the removal of the Oertz Rudder fittings, and making a Rudder as per attached blue print, and we shall be pleased to have your approval hereto.

Yours faithfully,

FOR AND ON BEHALF OF
JOSEPH CONSTANTINE STEAMSHIP LINE LTD.

W.S. Smith DIRECTOR

(W.S. SMITH).



© 2021

Lloyd's Register
Foundation

W51-0117

Special Damage or Repair Fee (if any).....£

17 JUN 1937

Referred to the Chief Ship Surveyor

Handwritten: 16 JAN 1873
Handwritten: Submitted for approval at
Handwritten: Amended

Handwritten: 20/1

"KIRKWOOD"

Altns to rudder

Ltr.15/1 Ansd. 20/1

1 plan

p.c. Mdb.



© 2021 Lloyd's Register Foundation

MIDDLEBROUGH
MAYTIME BRIDGE

CONSULTATIVE LINE