

W513-0024

F.E.

of Ship Surveyor

Received from Chief Ship Surveyor

AME *Stl. Lu. Lc. M/V "CABO SANTO TOME"* Rpt.

*Bbo*  
*Bdoc*

No. *8054*  
*4256*

Acts of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Table No.

*1659<sup>m</sup>*

Depth "d"

*4.41<sup>m</sup>*

Description

*Bull angle frames as approved*

Cardinal No.

*4494<sup>m</sup>*

Proportions

Length  
Depth

*13.03*

Heerstrake *as approved.*

*A doubling plate has been fitted on the garboard ke on port side in way of submarine signalling gear. the work could not be examined when completed the*  
*Yours recommend same be examined at next dry docking.*

This vessel appears to have been built in accordance with the and the approved plans, and it is submitted she is eligible to

sed **✠ 100 A 1 (Steel)** with freeboard," as

ended. The Summer freeboard of *12ft - 0½in* from centre of disc of statutory deck line at — deck, now marked on the

sides, to be inserted in the classification certificate, and

in the Register Book, and further, the remaining freeboards,

on the accompanying verification form to be inserted in the

ate of classification.

*(Stl - Weather Dk pt w.s.), 3<sup>rd</sup> Dk (Stl) in forward holds.*

*B. 419' 1790t, Tanks in way of tunnels 651t*

*T.K, 9 B.H, pt Cem, Lloyds A & C.P.*

*B 270', F 55.*

Lloyds Register  
Foundation  
20.1.32