

WS13-0030

1E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

*Cabo Santo Tome Rpt. Rbo No. 8054.*

Notes of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

of Engine

*oil engines 2 S.C.D.A.*

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner *no*

If fitted with an outside gland of approved type *Yes.*

RETAIN

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ SMC 12.31.*

*The Doukey Boiler is for domestic purposes only & the Pressure is not to be recorded in the Register Book.*



© 2020

Lloyd's Register Foundation

*Pl.*

*19/1/32*