

Lloyd's Register of British & Foreign Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square, West,
Belfast



S.S. "San Francisco"

The Superintendent of this vessel desired that no fibre fastenings be fitted in beams, but a separate hole be drilled for each armoured cable, & then the cables gathered together taut, & clipped securely to the underside of deck.

This arrangement in my opinion made a good sound job, and prevents any chafing taking place

A. S. Thomas.



© 2021

Lloyd's Register
Foundation

W52-0043