

1

Sent to Chief Surveyors

Received from Chief Surveyors **19 AUG 1941**VESSEL'S NAME KYMA Report LIV. No. 116451**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey DOCKING When due

*Subject to the rudder being lifted and repairs as necessary to  
pinbles + gudgeon bushes at the next dry docking.*

*WOL*  
*18.8.41*

The Certificate of Classification to  
be endorsed "*Cargo bunnens not  
fitted*" and the same notation to be  
printed in the Register Book.



© 2021

Lloyd's Register  
Foundation

WS2-01TS

Stringers

Have Ventilators and their Coamings been examined  
and found efficient? *yes*

at other places