

2m.11.35.

The class is subject to the
DONKEY BOILER
not being used again.

Received by Chief Engineer Surveyor

5E

16 NOV 1936

Received from Chief Engineer Surveyor

VESSEL'S NAME

Hannah

Rpt.

Auc.

No. 20681

" " 20718

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/24)

RETAI

~~DAMAGE &~~ WEAR AND TEAR.

Nature of Survey

A second hand donkey boiler with additional strengthening fitted in accordance with the appearance plan now fitted on board in lieu of the original boiler.

It is submitted the vessel is eligible to remain as classed with record of Survey DBS 10.2 as recommended without special conditions.

June-in R.B. NDB 32 fitted 10.36
100 lb.

WS24-0086

Lloyd's Register
Foundation
16/11/36