

TELEPHONE AVENUE 1270.

Handed in by
Mr. Caring.

CUNARD HOUSE,

LEADENHALL STREET,

LONDON, E. C. 3.

"Pat Jackson"

The Doctor's statement is that the severe
lurch occurred about 11.30 P.M. on the
13th. March & that the engines were
stopped at the time.

This does not agree with Deck & Engine
Room Logs as both engines were running at
that time.

At 2.25 A.M. on the 14th. the Pat Engine
was stopped for 10 minutes to adjust
the Governor which was thrown out of
action by the heavy pitching & rolling.
Mr. Rooper recollects the incident, but
does not remember the hour, he was
asleep at the time.

The severe lurch
alarmed his daughter & her friend.
They were in an adjoining Cabin
& they both ran into Mr. Rooper's

MS28-0276

room where they remained for some time.
It does not appear that those on
board thought of any special cause
for the severe roll. The weather was
quite bad at the time.



© 2021

Lloyd's Register
Foundation