





S/S. "MANIPUR"

The Deep tank has now been dispensed with and rotated

ANCHORS.

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

The approved plans are forwarded herewith.

F. one doubling 2'-6"

32 boys

and replaced. 1. found a 1 rose name for me.



"S. MANIPUR"Repairs

Four rudder bushes renewed.

Old studs in cables renewed or hardened up.

Anchor crown shackle pin port side renewed.

Wing plates of stoke hold bulkhead cropped and part renewed.

Saloon deck house port side doubling plate fitted on coaming full length of house.

A number of minor repairs in addition to the above now effected throughout vessel.



© 2020

Lloyd's Register

Foundation

W 530017 (3/3)