

Subject to Collision damage on starboard bow

REGISTER LIVERPOOL.

# Lloyd's Register of Shipping.

201, Tower Building,

Liverpool, 3. 31st May, 1937.

*Encl:*

LLOYD'S REGISTER  
1 - JUN 1937  
Ansd.  
LONDON

Dear Sir,

I beg to acknowledge the receipt of your letter of the 29th instant regarding the repairs carried out at Calcutta on the boilers of the steamer "MANIPUR" and as requested have obtained from Messrs. Goodwin Hamilton & Adamson Ltd., some of the defective rivets, which have today been forwarded to the Society's Glasgow Office for examination by Mr. Lewis.

A memo from the Consulting Engineers is enclosed, from which it will be noted that they have arranged for the Chief Engineer to furnish the London Surveyors with a sample of Boiler Water as may be required, it being understood that the vessel is now at Tilbury.

I am, Dear Sir,

Yours faithfully,

*J. Keith*  
Secretary to the  
Liverpool Committee.



Lloyd's Register  
Foundation  
W53-01043

The Secretary.  
LONDON.

Referred to the Chief Engineer Surveyor

1 - JUN 1937  
also for Mr. Spinks to note.

*Adm*

*Thorne Jones*  
*Sud. Clerk*

*Sample for*  
*hipples*  
*for Both*  
*in all*



© 2020

Lloyd's Register  
Foundation

ENGINEER

J.

LIABILITY WILL

"WINDSOR," "LIV  
"WINDSOR," GL  
W 0020 CENTRAL.

FAMILT  
CONSULTING  
LARD B

AND AT 1

We

We e

UP LON

ay requ