

SUMMARY OF DAMAGE REPAIRS:—

Shell Plates.

Frames.

R. Frames.

Floors and

Beams.

Inner Bottom

Dk. Plates.

Other Items:—

Engine
Boiler

No.

S.O. 99/38

Made by

John Brown & Co.

For H

For

S.S. "Huddersley"

G.L.

Report No.

60730

It is submitted that ~~a copy of~~ this Report be
forwarded to the G.L. Surveyors for their
~~returned~~ guidance and for completion.

Date

23/2/39.

© 2020

Lloyd's Register
Foundation

W53 0085