

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

12th November, 1935.

Dear Sir,

I have to acquaint you I am in receipt of a report from the Society's Surveyor at Fremantle from which it appears that the steamer "MINDEROO" has been examined as far as practicable afloat and extensive damage was found to the shell plating, framing, floors &c., in way of Nos. 4 & 5 double bottom tanks and to the shell plating in No. 3 hold through resting on a sand bank. Temporary repairs were effected and, in the Surveyor's opinion, the vessel is fit to be towed to port of repairs and he recommends permanent repairs be carried out at the earliest opportunity.

It appears that the vessel is to be towed to Singapore, and, in the circumstances, I shall be glad if you will give the case attention.

I am, Dear Sir,

Yours faithfully,

Clerk to the
Classification Committee.

J. Wormald Esq.,
SINGAPORE.



© 2020

Lloyd's Register
Foundation

W537-0248

YH50-532W

blowing h. Fremont
ach. photos.
15/11/5 ✓

THEY WOULD NOT

11. French 2nd, E.C. 3.

English to Foreign

Y900



© 2020

Lloyd's Register
Foundation