

COPY.

-8 NOV 1935

Lloyd's Register of Shipping.



Port FREMANTLE. W. A.

7th October, 1935.

This is to Certify *that I have*

examined the Steel Screw Steamer "MINDEROO" of London, 2720 tons

registered, for the purpose of ascertaining the nature and extent of damage alleged to have been caused when the vessel resighted at Port Hedland on 14th September, 1935.

that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all temporary repairs recommended by me have been completed to my satisfaction, and

I have Recommended that she be classed as fit to be taken to Port of Repair, and further that she be continued as

such, subject to permanent repairs being satisfactorily carried out at the earliest opportunity.


and fit to carry dry and perishable cargo.

Wm. G. Davies.

Surveyor to Lloyd's Register.

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
neither the Committee nor the Society are under any circumstances whatever to be held responsible for
any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
document, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or
of its Officers or Agents of the Society."

Attach to Rept. Nos 803 & 804



**Lloyd's Register
Foundation**
W537-0268