

Engineer Surveyor

Muderoo.

Received from Chief Engineer Surveyor

Rpt.

Fr.

No. 503

the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

advisement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points stated in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE TO ENGINES AND BOILERS.

This vessel is reported by the *Remaitte* Surveyor sustained damage to *Machinery* through *pounding*


Temporary repairs have been effected to his satisfaction to enable her to proceed on her voyage to *Singapore in tow.*

The Surveyor recommends *permanent repairs at earliest opportunity*

It is submitted *action be deferred.*

main engines are totally disabled - bed plate broken, shafting bent, main steam pipe damaged etc.

J.A. 8/10/21



© 2020

WS37-0270

Lloyd's Register
Foundation