

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SHIP'S NAME Steel SS "MOERDYK"

Rpt. Rot.

No. 1135A

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.
ex "Denderah"

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey.....

results 27/8/20
The Surveyors should be requested to state whether web frames are fitted forward as shown on plans, whether a hand pump has been fitted to fore peak tank tops, & whether the insulation in hold abaft engine room was fitted before present survey. If so the surveyors should state whether any of the insulation has been removed for examination of steelwork.

the
They should also state whether all the requirements of section 48 of rules, for vessels not built under Survey, have been complied with

L. Rot. 13th



2021
13-8-20

Lloyd's Register
Foundation
W547-0174