


Received from Chief Ship Surveyor

28 MAY 1927

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Figure of Survey

It is submitted action be deferred.



Wanda.
27. 5. 27.

To complete the survey: E & B room tank and hand pump to fore peak

F.T.O.

Amend record OKs

1 A. M. U. 10:26

Stl. S.S. "KAMBOYE".

to test, W.T. doors, and ventilator covers to examined except in wells.

All holds to scale from 2nd deck to ceiling, wood on tunnel top to renew in way of hatches, engine room tank top to scale and engine room sides to scale where necessary.

Casing top plate at each side of engine room skylight to renew.

Stiffeners on hatch coamings to fair as necessary.

Vessel to be placed in dry dock for permanent repairs (defective rivets on starboard side of No.3 hold) on her return to Antwerp.

Worms
27.5.27



© 2021

Lloyd's Register
Foundation

W55-0049(212)