

2m.10.39.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

MANSEPOOL

Report

GIB. 2643
LIV. No. 114350

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE + COMP^N 1ST S.S. N^o 3 When due 2-40

Subject to temporary repairs to stern frame, at keel being specially examined at the next dry-docking and to rudder stock at top in way of the quadrant being examined in about 6 to 12 months time (lifting hole in way)

WAG
24.6.40

WAG



© 2021

Lloyd's Register
Foundation

W55-0087