

COPY.
PORT OF

GRAYSON, ROLL AND CLOVER DOCK LTD.

WORKS
LIVERPOOL
NORTH SANDHILLS
DOCK 119

WORTHINGTON DOCK
DOCK 120

WORTHINGTON DOCK
DOCK 121

WORTHINGTON DOCK
DOCK 122

WORTHINGTON DOCK
DOCK 123

WORTHINGTON DOCK
DOCK 124

TELEPHONE
WORTHINGTON DOCK

TELEPHONE
WORTHINGTON DOCK

DIRECTOR
WORTHINGTON DOCK
DOCK 119
DOCK 120
DOCK 121
DOCK 122
DOCK 123
DOCK 124

DOCK 119
DOCK 120
DOCK 121
DOCK 122
DOCK 123
DOCK 124

DOCK 119
DOCK 120
DOCK 121
DOCK 122
DOCK 123
DOCK 124

DOCK 119
DOCK 120
DOCK 121
DOCK 122
DOCK 123
DOCK 124

DOCK 119
DOCK 120
DOCK 121
DOCK 122
DOCK 123
DOCK 124

18th June 1940.

SANDHILLS
LIVERPOOL DO

Dear Sirs,

I am directed to acquaint you that the Committee have had before them a report from the Society's Surveyors at this Port on the machinery of the "MANSEPOOL", from which it appears that, in view of the condition of the cracked webs in the bottom of the L.P. cylinder, it is recommended that, it should be again examined about the end of June 1942; and the Committee have accordingly continued the vessel's classification in the Register Book subject to this being done.

I am, Dear Sirs,

Yours faithfully,

Secretary to the
Liverpool Committee.

Messrs. Ropner S.S.Co.

WEST HARTLEPOOL.

We are,

Yours faithfully,



© 2021

Lloyd's Register
Foundation

W 55-0088 89