

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

4th June, 1917.

Dear Sirs,

I am in receipt of the telegram received from you
M. to-day as follows, viz.,

"Kewickhall 21 Supplement Owners' representative
"requests reassignment freeboard per Circular 1292
"forward instructions stop minimum number and position
"of scuppers required from shelter tween decks."

and in reply thereto I am directed to acquaint you that
you should be guided by Circular 1292 and forward the
necessary report on form 11b, as early as possible, together
with a statement as to what alterations are arranged for,
and in progress, in order that amended freeboards may be
assigned, leaving only the completion of the alterations
to be reported with the verification of marking form.

As regards the scuppers required from the shelter
tween decks leading to the bilges, I have to inform you that
these should be fitted on each side of Nos. 2 and 3 holds
and Engine and Boiler spaces. If, however, there are any
tween deck divisions to prevent water reaching these
scuppers, additional ones should be fitted to Nos. 1 and 4
holds.

I am, Dear Sirs,

Yours faithfully,

The Surveyors,
MIDDLESBROUGH.

WS51-0204

© 2021

Lloyd's Register
Foundation
Secretary.