

LLOYD'S REGISTER
LONDON.

Time of Receipt 2-16

REC'D JUN 4 1917

ANSR - 4

TELEGRAM.

POST OFFICE



TELEGRAPHS.

Office Stamp.



Handed in at

Office of Origin and Service Instructions

Words

Charges to pay

135 Middlesboro

30

THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM.

Received here at

2 4 P .M.

TO

Committee

From London

Repurick Hall 21 Supplement
 owners representation requests
 Reassignment free board per
 Circular 1292 forward instructions
 Stop minimum number and position
 of Scuppers required from Shelter tween
 decks Survivors



© 2021

Lloyd's Register
Foundation

WS51-0205

Referred to the Chief Ship Surveyor.

Cs-A

JUN 4 1917

usual stock letter in reply regarding
Circular 1292.

Scuppers from the tween deck
leading to the bigges
should be fitted on each side
to ^{Nos 2 & 3} holds and E & B space.
If however there are any tween
deck divisions to ~~prevent~~ ^{prevent} water
reaching these ^{scuppers} H. 6. 17
scuppers, additional
ones should be fitted
to Nos 1 and 4 holds.

RETAIN



© 2021

Lloyd's Register
Foundation