

30 NOV 1933 1

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl. S. AGAMEMNON Rpt. Rev. No. 3548

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

DAMAGE.

Particulars of Survey _____

Damage through Grounding, Collision, Fire. (See 13002)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- Vessel placed in drydock, bottoms cleaned coated. Bilge Keels repaired, Ceiling in hatches part renewed and minor repairs effected.

The Surveyor recommends some indented plating on port side forward to be dealt with at the owner's convenience

It is submitted the vessel is worthy to remain as classed with record of Survey 11.33. ^{subject} as recommended, but without other conditions.

100 A. 1. } subject etc
11.33 Rev } without etc



© 2021 Lloyd's Register Foundation W553-0003