

28 DEC 1933

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. Sr. "BROOM FLEET" Rpt. Hul. No. 44303

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ture of Survey


The Hull Surveyors report this vessel placed in dry dock, bottom cleaned and coated and on account of damage through heavy weather, 1 shellplate has been renewed, 10 shell plates repaired, about 1450 rivets renewed and 29 tank lugs repaired and minor repairs carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 12,33.

100A1
12,33 Goo

The Certificate of Classification to be endorsed "Cargo buttons not tested" and the same notation to be entered in the Register Book.

Casualty
notice
Sent 11.34



© 2021

Lloyd's Register
Foundation

20.12.33