

S.S. "BRAEMORE"

-----

The Electric Lighting Installation of this vessel was fitted at Hull but after a short trial it was found that the engine was running hot and the governor not working.

It was stated that the vessel was to proceed to Dublin, and the report was sent to the Dublin Surveyor on 1st November 1921 for his information.

The report does not appear to have been returned to this Office and the Surveyorship at Dublin is now Non-Exclusive.

*Submitted enquiry should be made of M. Foster who was the Surveyor at Dublin at that time*

*ARK*

*22.11.23*

*L 22/11/23*



© 2021

Lloyd's Register

FD 555 0089