

S.S. "Braemore"

Sps. —

The Hull Surveyors state that after a short trial of the electric lighting installation it was found that the engine was running hot and the governor not working, and that a further trial will be necessary after adjustment.

The vessel has now left for Dublin. It is submitted that a copy of the letter from the Hull Surveyors and also the Spensish report be forwarded to the Dublin Surveyors for their guidance and for completion.

Sent 1/11/21

L. J.
1/11/21.



© 2021

Lloyd's Register
Foundation