

W558-0028

Surveyors

Received from Chief Surveyors

NAME

S. S. "Foresthill"

Report

Gls.

No. 44064

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey

1st Entry

When due

✕ 100A1 (Steel)

1 DK (steel)

• All D.B. 20H' 454t. F.P.T. 72t. A.P.T. 35t.

F.K. 4 B.H. cum. Lloyds A.C.P. P. 17' B. 58' F 23'

the Certificate of Classification, to be endorsed  
"large buttens not fitted," and the same  
action to be printed in the Register Book.



© 2021

Lloyd's Register  
Foundation

4.12.74