

s of particulars of Casualty This vessel is reported to have
been sunk by submarine off the Spanish coast on
the 5th September 1939

2m, 10, 35.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME **BOSNIA**

Report **Liv.** No. **112814**

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey **Docking & Repair.** When due _____

Subject to No 1 plate in 3rd strake below main sheer (s.s) (BW 5,39)
Being specially examined at next dry docking & to include
shell plating etc at after end of No 1 hold (s.s) being dealt
with at the Special Survey.

ell

pld

Amend S.R.L as above



20 7039 © 2020

Lloyd's Register
Foundation
W560-0099