

Damage due to fouling over

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

rope
jacking. Screw shaft examined
Repairs effected

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

Subject to Screw shaft
false stuffing box being
bed at next drydock.

S. 9. 29

Hm

23. 9. 29

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation