

5m.10.30.

W579-0131

18 APR 1932

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "HALIARTUS" Rpt. Mdb. No. 14594

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Signature of Surveyor

The class is subject to indented plates on port and starboard sides forward being dealt with at the Owners' convenience.

The 1st S.S. No.3, due 5.31, has been partly held.

Permanent repairs are required to damaged shell plating etc. on starboard side.

The Middlesbrough Surveyors now report the vessel examined afloat, the special survey further advanced and repairs effected to the tank margin and lower deck in way of coal shoot.

Temporary repairs have been effected to the bracket floors in Nos. 1, 2, 4 & 5 double bottom tanks.

The indented and damaged shell plating has not been dealt with.

To complete the survey:- Nos. 1, 2, 4 & 5 double bottom tanks to be cleaned, riveting of bracket floors to test and repair and cement fillets to be made good.

It is stated the survey will be completed on the vessel's return in about three months' time.

The year of grace will expire 5.32.

It is submitted action ^{MIGHT} be deferred.