

W 580-0171

4 E

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

16 JUN 1933

VESSEL'S NAME

Requena.

Rpt.

Lon

No.

9858

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*) The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24.5.92.

Nature of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

See endorsement dated 23.5.33.

The London Surveyor now reports that the Engines & Boilers have been generally examined & found in fit condition for the voyage to Nakh where she will be broken up. Substantiated action be deferred.

J. H. 16/6/33

Lloyd's Register
Foundation