

5E

24 JUN 1931

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME s.s. "JOHANNA"

Rpt. Rotterdam

No. 20398

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE & WEAR AND TEAR.

The Rotterdam Surveyors report that on account of damage through propeller striking quay wall the screwshaft has been examined and one propeller blade found slightly damaged.

BS due 5,31 stated will be held on return from present voyage.

It is submitted the vessel is eligible to remain as classed without fresh record of Survey as recommended.

S 6,31.



HR
© 2021
23.6.31.

Lloyd's Register
Foundation
W582-0025